SCTE STANDARDS

Interface Practices Subcommittee

AMERICAN NATIONAL STANDARD

ANSI/SCTE 88 2012 (R2021)

Test Methods for Polyethylene Jacket Longitudinal Shrinkage

NOTICE

The Society of Cable Telecommunications Engineers (SCTE) Standards and Operational Practices (hereafter called "documents") are intended to serve the public interest by providing specifications, test methods and procedures that promote uniformity of product, interoperability, interchangeability, best practices, and the long term reliability of broadband communications facilities. These documents shall not in any way preclude any member or non-member of SCTE from manufacturing or selling products not conforming to such documents, nor shall the existence of such standards preclude their voluntary use by those other than SCTE members.

SCTE assumes no obligations or liability whatsoever to any party who may adopt the documents. Such adopting party assumes all risks associated with adoption of these documents and accepts full responsibility for any damage and/or claims arising from the adoption of such documents.

NOTE: The user's attention is called to the possibility that compliance with this document may require the use of an invention covered by patent rights. By publication of this document, no position is taken with respect to the validity of any such claim(s) or of any patent rights in connection therewith. If a patent holder has filed a statement of willingness to grant a license under these rights on reasonable and nondiscriminatory terms and conditions to applicants desiring to obtain such a license, then details may be obtained from the standards developer. SCTE shall not be responsible for identifying patents for which a license may be required or for conducting inquiries into the legal validity or scope of those patents that are brought to its attention.

Patent holders who believe that they hold patents which are essential to the implementation of this document have been requested to provide information about those patents and any related licensing terms and conditions. Any such declarations made before or after publication of this document are available on the SCTE web site at https://scte.org.

All Rights Reserved
© 2021 Society of Cable Telecommunications Engineers, Inc.
140 Philips Road
Exton. PA 19341

1.0 DOCUMENT TYPES AND TAGS

Document Type: Specification		
Document Tags:		
☐ Test or Measurement	☐ Checklist	☐ Facility
☐ Architecture or Framework	☐ Metric	⊠Access Network
☐ Procedure, Process or Method	☐ Cloud	☐ Customer Premises

2.0 DOCUMENT RELEASE HISTORY

Release	Date
SCTE 88 2003	4/4/2003
SCTE 88 2007	12/29/2007
SCTE 88 2012	12/31/2012

Note: This document is a reaffirmation of SCTE 88 2012. No substantive changes have been made to this document. Information components may have been updated such as the title page, NOTICE text, headers, and footers.

ANSI/SCTE 88 2012 (R2021)

TABLE OF CONTENTS

Section	Title	Page
1.0	DOCUMENT TYPES AND TAGS	II
2.0	DOCUMENT RELEASE HISTORY	II
3.0	SCOPE	2
4.0	EQUIPMENT	2
5.0	TEST SAMPLES	2
6.0	TEST METHODS	2
7.0	INSPECTION	3

3.0 SCOPE

3.1 The purpose of this test is to determine the amount of shrinkage of the jacketing material used on coaxial drop and distribution cables. This test procedure is applicable for use on either drop or distribution coaxial cables employing polyethylene (PE) jacketing material.

4.0 EQUIPMENT

4.1 A full draft circulation oven with a removable, thin, flat, horizontal bed of ceramic or glass beads. The oven shall be capable of meeting the following requirements for a period of four (4) hours.

 100 ± 1 °C (212 ± 2 °F) For Low Density Materials: $\leq 0.940 \text{ g/cm}^3$ @ 23 °C (74 °F) 115 ± 1 °C (240 ± 2 °F) For High and Medium Density Materials: $\geq 0.940 \text{g/cm}^3$ @

Band saw or hack saw

23°C (74°F)

4.3 A temperature indicator in the range of the specified temperature shall be used.

5.0 TEST SAMPLES

4.2

- Test samples shall be 6 ± 0.5 inches $(150 \pm 10 \text{ mm})$ long cut from the first 100 feet of the cable reel.
- 5.2 Test samples shall be cut clean and perpendicular to the longitudinal axis of the cable. The ends of the cable samples are to be clean and square.

6.0 TEST METHODS

- 6.1 Preheat the full draft circulating oven with the removable bed of ceramic or glass beads in the oven for 60 minutes (1 hour) to the temperature required.
- Place the test samples on the bed in the oven without touching one another or anything else other than the bed.

ANSI/SCTE 88 2012 (R2021)

7.0 INSPECTION

- 7.1 The test samples shall remain in the oven for four (4) hours at the specified temperature. Then without disturbing the test samples on the bed, remove the bed and test samples together. The bed and test samples should be placed on a flat horizontal surface that is in still air at room temperature.
- 7.2 After cooling for 60 minutes (1 hour) at room temperature, each specimen shall be measured for shrinkage of the jacket from each end of the outer conductor.
- 5.3 Record and document all measurements and observations.